

© JENCOM 2007  
Rivet Clinch Verification




FIG #1 - GOOD PART

Tracking Window

Pattern Inspection Window

Edge Measurement Windows (4) in total for demo.

© JENCOM 2007  
Rivet Clinch Verification




FIG #1 - DEFECTIVE PART